## Oil Field Environmental Incident Summary

**Responsible Party:** WATERWORKS CORRAL CREEK, LLC **Well Operator:** WATERWORKS CORRAL CREEK, LLC

Well Name: KLEEMAN SWD #1

Field Name: CORRAL CREEK Well File #: 90257

Date Incident:6/20/2014Time Incident:22:00Facility ID Number:County:DUNNTwp:147Rng:95Sec:19Qtr:

**Location Description:** 

Submitted By: Ken McGuire Received By:

Contact Person: Brent Lansberg

119 E. COURT STREET CINCINNATI, OH 45202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

**Distance Nearest Occupied Building:** 1000 Feet **Distance Nearest Water Well:** 200 Feet

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site Reported to NRC: Unknown

	Spillea	Units	Recoverea	Units	
Oil	3	Barrels	2	Barrels	
Brine	8	Barrels	6	Barrels	

Other

**Description of Other Released Contaminant:** 

Chilled Haite

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

none

Areal Extent:

Followup

**Units** 

## Potential Environmental Impacts:

oil and salt water residue

## Action Taken or Planned:

sucked up salt water and oil from ground with vac truck and had Bear Mountain LLC (701) 627-2494 clean up contaminated soil

Wastes Disposal Location: salt water and oil was injected into our disposal well. contaminated soil was taken to Nuverra solids disposal in Watford City

Agencies Involved:

## **Updates**

Date: 7/25/2014 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release, due to a tank overflow, remained on location according to the report. NDIC retains oversight.